
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls	Company: Savin	Date: <u>7/7/2009</u>
Test to be performed:  Smoke Dyed Water X	Ground Condition:  Dry ✓ Damp □ Wet □	Supervisor: JAW
Manhole_ID: S05QQ_004MH	Test ID: <u>D1032-015009</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S05QQ_006MH
0			Water Level	
196.1999969	10		Tap Break-in	From 2703 Chelsea
196.3999939			Dye Test Visible	@ TF - downspout
209.3000031			End of Survey	DYE TEST COMPLETED